

FPI and MPI of Cracks Under Coatings

by Scott Grendahl and Benjamin Hardisky

ARL-TR-4033 January 2007

NOTICES

Disclaimers

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

Citation of manufacturer's or trade names does not constitute an official endorsement or approval of the use thereof.

Destroy this report when it is no longer needed. Do not return it to the originator.

Army Research Laboratory

Aberdeen Proving Ground, MD 21005-5069

ARL-TR-4033 January 2007

FPI and MPI of Cracks Under Coatings

Scott Grendahl and Benjamin Hardisky Weapons and Materials Research Directorate, ARL

Approved for public release; distribution is unlimited.

REPORT DOCUMENTATION PAGE

Form Approved OMB No. 0704-0188

Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing the burden, to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports (0704-0188), 1215 Jefferson Davis Highway, Suite 1204, Arlington, VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to any penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.

PLEASE DO NOT RETURN YOUR FORM TO THE ABOVE ADDRESS.

1. REPORT DATE (DD-MM-YYYY)	2. REPORT TYPE	3. DATES COVERED (From - To)
January 2007	Final	1 June 2005–12 July 2006
4. TITLE AND SUBTITLE		5a. CONTRACT NUMBER
FPI and MPI of Cracks Under Co	oatings	
	-	5b. GRANT NUMBER
		5c. PROGRAM ELEMENT NUMBER
6. AUTHOR(S)		5d. PROJECT NUMBER
Scott Grendahl and Benjamin Ha	rdisky	581P31
·	•	5e. TASK NUMBER
		5f. WORK UNIT NUMBER
7. PERFORMING ORGANIZATION NAME	E(S) AND ADDRESS(ES)	8. PERFORMING ORGANIZATION REPORT NUMBER
U.S. Army Research Laboratory	•	A.D.I. TD 4022
ATTN: AMSRD-ARL-WM-MC		ARL-TR-4033
Aberdeen Proving Ground, MD		
9. SPONSORING/MONITORING AGENC	Y NAME(S) AND ADDRESS(ES)	10. SPONSOR/MONITOR'S ACRONYM(S)
U.S. Army Aviation and Missile	Command	AMCOM
Redstone Arsenal, AL 35898		11. SPONSOR/MONITOR'S REPORT NUMBER(S)
12 DISTRIBUTION/AVAILABILITY STAT		

12. DISTRIBUTION/AVAILABILITY STATEMENT

Approved for public release; distribution is unlimited.

13. SUPPLEMENTARY NOTES

14. ABSTRACT

The U.S. Army Aviation and Missile Research Development and Engineering Center requested that the U.S. Army Research Laboratory develop and execute a program designed to evaluate the performance of nondestructive inspection (NDI) techniques over typical army aviation paint systems. Corpus Christi Army Depot performs the majority of the current maintenance and overhaul operations on army aviation systems. This facility would greatly benefit in throughput and in reduction of hazardous waste generated if the removal of the applied coating systems could be avoided. The objective of this work was to evaluate the effect of not removing the most common currently approved aviation coating system on the NDI cycles. The test plan and methodology was created in conjunction with and approved through AMSRD-AMR-AE-F-M.

15. SUBJECT TERMS

flashjet, rotor-blade composite, mechanical properties

16. SECURITY CLA	SSIFICATION OF:		17. LIMITATION OF ABSTRACT	18. NUMBER OF PAGES	19a. NAME OF RESPONSIBLE PERSON Scott Grendahl
a. REPORT	b. ABSTRACT	c. THIS PAGE			19b. TELEPHONE NUMBER (Include area code)
UNCLASSIFIED	UNCLASSIFIED	UNCLASSIFIED	UL	72	410-306-0819

Standard Form 298 (Rev. 8/98) Prescribed by ANSI Std. Z39.18

Contents

Lis	t of Figures	v
Lis	t of Tables	vii
1.	Background	1
2.	Development of the Test Plan	1
3.	Materials Selection and Procurement	3
4.	Background of Fatigue-Generated Cracks	3
	4.1 Bar Preparation	4
	4.2 Crack Initiation and Extension	4
	4.3 Creation of Fatigue Cracks	5
	4.4 Light Optical Photometer	12
5.	Materials Pretreatment	12
6.	FPI/MPI and Light Measurements	12
7.	Painting	13
8.	Crack Extension After Painting	13
9.	Plastic Media Blasting	14
10.	Chemical Removal of Paint	16
11.	Results	16
	11.1 Aluminum	16
	11.2 Titanium	20
	11.3 Magnesium	25
	11.4 Steel	33

12.	Discussion	38
	12.1 Scope	38
	12.2 Effect of Performing FPI Over Paint	38
	12.3 PMB	39
	12.4 Chemical Removal	39
13.	Conclusions	39
	13.1 FPI	39
	13.2 MPI	39
14.	References	40
Apj	pendix. Schematics of the Incremental Formation of the Specimens	41
Dis	tribution List	60

List of Figures

Figure 1.	Flow diagram for evaluating FPI and MPI of cracks under coatings	2
the in	Schematic of the cross section of a typical fatigue-cracked test specimen depicting cremental removal of material from the top surface and its corresponding effect on	
	-length reduction	
Figure 3.	Al bar no. 7 after initiation and extension (shows crack at its final length.)	.18
Figure 4.	FPI of Al bar no. 7 after initiation and extension.	.18
acquir meast	Al bar no. 7 illustrating the manner in which the brightness measurements were red. The top dot represents the area the spotmeter was focused for the background arement, and the bottom dot represents the area from which the crack measurement cquired	.19
Figure 6.	FPI of Al bar no. 7 crack after anodizing.	.19
Figure 7.	FPI of Al bar no. 7 crack after painting.	.20
	FPI of Al bar no. 7 after PMB. The crack can be observed visually, but no tion can be observed	.21
	FPI of Al bar no. 7 performed after the bar had been processed in paint stripper and he bar had been mechanically flexed	
	FPI of Al bar nos. 8, 9, and 10—the bars with cracks extended ~0.050 in after ng—performed after the bars had been painted and the cracks mechanically flexed	.22
Figure 11	. Titanium bar no. 6—0.1-in crack after initial crack extension	.22
Figure 12	FPI of titanium bar no. 6—0.1-in crack after initial crack extension	.24
taken	FPI of titanium bar no. 6 showing areas where brightness measurements were. The top spot is the brightness of the crack, and the bottom spot (below the crack) ere the background reading was taken.	.24
Figure 14	. FPI of titanium bar no. 6 after painting	.25
Figure 15	. FPI of titanium bar no. 6 after the painted bar had been extended by 0.5 in	.26
Figure 16	. Optical micrograph of titanium bar no. 6 showing the extended crack after PMB	.26
	. FPI micrograph of titanium bar no. 6 after PMB and mechanical flexing. Initial roduced no visible indication after PMB.	.27
_	FPI micrograph of titanium bar no. 6 after PMB and chemical-stripper ssing. The results are similar to those after painting and crack extension	.27
Figure 19	. Magnesium bar no. 2 with a 0.2-in crack length.	.29
	FPI micrograph of cracked Mg bar no. 2 after the crack was initiated and ded to the desired length	.29

Figure 21. FPI micrograph of cracked Mg bar no. 2 depicting the typical locations of the light measurements. The top spot is the brightness of the crack, and the bottom spot (below the crack) is where the background reading was taken.	.30
Figure 22. FPI micrograph of cracked Mg bar no. 2 after the Tagnite coating.	.30
Figure 23. FPI micrograph of cracked Mg bar no. 2 after the application of the coating system. No crack can be observed, and the absorption of the penetrant by the coating is evident.	.31
Figure 24. FPI micrograph of cracked Mg bar nos. 3, 6, and 7 after crack extension under the coating system. Cracks can be observed; however, the absorption of the penetrant by the coating is still evident.	.32
Figure 25. Typical FPI results after PMB, chemical processing, and mechanical flexing to remove the plastic media from within the cracks. Results shown for Mg bar no. 2 after soaking in paint stripper ~24 hr.	.32
Figure 26. Typical FPI results after crack extension under the coating, PMB, mechanical flexing, and chemical-stripper processing. Results shown for Mg bar nos. 3, 6, and 7 after soaking in paint stripper ~24 hr.	.33
Figure 27. Bar no. 3 after initiation and crack extension—typical fatigue crack generated in steel.	.35
Figure 28. Steel bar no. 6 after initial crack extension—0.2 in crack. Typical FPI visual results on steel fatigue cracks.	.35
Figure 29. Typical FPI micrograph of steel showing the areas where brightness measurements were taken on this bar. The top dot (on the crack) is the crack brightness measurement location. The bottom dot (below the crack) is the background measurement location.	.36
Figure 30. Bar no. 6 after the initiation and crack extension. Typical baseline visual MPI micrograph on steel	.36
Figure 31. Bar no. 6 after the 0.050-in crack extension. Typical visual MPI micrograph after crack extension.	.37
Figure 32. Typical visual MPI micrograph after the application of the second layer of paint. All traces of the crack indication are gone	.37

List of Tables

Table 1. Polishing, crack initiation, and crack extension data for aluminum bars	6
Table 2. Polishing, crack initiation, and crack extension data for magnesium bars	7
Table 3. Polishing, crack initiation, and crack extension data for titanium bars	7
Table 4. Polishing, crack initiation, and crack extension data for steel bars	8
Table 5. Aluminum grinding data	9
Table 6. Magnesium grinding data.	9
Table 7. Titanium grinding data	10
Table 8. Steel grinding data	11
Table 9. Data after paint crack extension	15
Table 10. Aluminum spotmeter readings	17
Table 11. Titanium spotmeter readings.	23
Table 12. Magnesium spotmeter measurement.	28
Table 13. Steel spotmeter measurements.	34

INTENTIONALLY LEFT BLANK.

1. Background

The U.S. Army Aviation and Missile Research Development and Engineering Center (AMRDEC) requested that the U.S. Army Research Laboratory (ARL) develop and execute a program designed to evaluate the performance of nondestructive inspection (NDI) techniques over typical army aviation paint systems. Corpus Christi Army Depot performs the majority of the current maintenance and overhaul operations on army aviation systems. This facility would greatly benefit in throughput and in reduction of hazardous waste generated if the removal of the applied coating systems could be avoided. The objective of this work was to evaluate the effect of not removing the most common currently approved aviation coating system on the NDI cycles. The test plan and methodology was created in conjunction with and approved through AMSRD-AMR-AE-F-M.

2. Development of the Test Plan

The test plan was developed by utilizing the prior research and development of Aeronautical Design Standard 61, ADS-61-PRF (1), specifically those sections dealing with fluorescent penetrant inspection (FPI) method, the creation of standardized cracks in specific sizes, and nonbiased, quantitative, light photometer measurement. A flow chart is provided for reference purposes (figure 1) and the test matrix is summarized as follows:

- Objective: Evaluate the effect of surface paint systems on FPI and magnetic particle inspection (MPI) performance in aviation maintenance and overhaul operations.
- Materials/Condition: 2024-T3 Al anodized in accordance with (IAW) MIL-A-8625 (2) prior to painting, bare Ti-6-4, AZ31B Mg Tagnite*-coated prior to painting, and cadmium-plated 4340 steel IAW SAE-AMS-QQ-P-416 (3) at a 40–50 Rockwell hardness (HRC) level.
- Test Specimens: The specimens were utilized to generate fatigue cracks of a known size. Three sizes for each material were used: 0.025, 0.1, and 0.2 inches in length. Two samples at each length for each material were used. Specimens have typical machined surface finishes.
- Geometry: $1 \times 6 \times 0.4$ -in flat specimens. There is no reason to believe a flat surface isn't the worst case for crack detection.

^{*}Tagnite is a registered trademark of Technology Applications Group.




Figure 1. Flow diagram for evaluating FPI and MPI of cracks under coatings.

- Primer: Epoxy primer (MIL-P-23377 [4], Type II, Class C) to dry film thickness of 1–1.5 mil.
- Topcoat: New chemical agent resistant coating (CARC), MIL-C-64159 (5), to a dry film thickness of 2–2.5 mil. Apply MPI coating in layers to evaluate the results incrementally.
- Drying Conditions: Air-dry the primed and painted specimens for 1 week, and then bake the specimens at 150 °F for 1 week.
- Cleaning: Simulate conventional maintenance cleaning cycles prior to FPI inspection.
- FPI: IAW the standard method of ADS-61-PRF.
- MPI: IAW ASTM-E-1444 (6). After performing baseline MPI, paint and cure the three cracked test specimens with conventional operations. Perform MPI again after the paint and cure cycle. Add additional paint thickness and cure cycles while performing MPI in between stages. Record coating thickness and record observations with text and photographs. Determine the thickness at which MPI becomes detrimentally affected. Cycle cracks to extend ~0.050 in. Repeat MPI cycle to determine the thickness at which MPI becomes detrimentally affected.

3. Materials Selection and Procurement

Four U.S. Army aviation relevant materials were selected to be incorporated into the test protocol. These materials were 2024-T3 Al anodized IAW MIL-A-8625 prior to painting, bare Ti-6-4, AZ-31B Mg Tagnite-coated prior to painting, and cadmium-plated 4340 steel IAW SAE-AMC-QQ-P-416 at 40-50 HRC. Twenty samples of each material were procured. The specimen size was $1 \times 0.4 \times 6$ in. These specimens were utilized to generate fatigue cracks.

4. Background of Fatigue-Generated Cracks

These precracked test bars are not off-the-shelf items. Typical nondestructive testing (NDT) standards incorporate thin aluminum or chrome-plated substrates pressure-dimpled from the back side or electrically discharged (sparked) to generate cracks on the front side of the plates. Various crack sizes can be generated from these methods, but they are not "tight" because of their inherent material properties (low modulus of elasticity) and the fact that they are not generated from metal fatigue cycling. There are also NDT test specimens that contain electro-discharge machining slots that also do not have the same tight geometry as fatigue cracks and are limited in their usefulness. When performing FPI on aircraft components, and especially when

inspecting helicopters, fatigue cracks are the main concern. The sizes of the cracks were predetermined by AMRDEC and based upon previous research and risk concerns. The concept behind the original crack-size determination is that the smallest crack size reliably observable by the utilized technique must be determined (in this case by FPI and MPI), and then that crack size is used to verify that any process modification (such as the process being performed over paint) does not detrimentally effect the observation of an indication. In this case, an ~0.025-in crack is the smallest detectable (at a 95% probability of detection [POD] level), and cracks of ~0.05 in should be readily observable and distinct at the 100% POD level. Cracks of 0.1 in and 0.2 in are considered large for these techniques and also should not be overlooked. They were included to provide a measure of any detrimental effect.

4.1 Bar Preparation

For several reasons, the bars needed to be mechanically finished prior to exposure to cyclic fatigue. During the extension process, the crack had to be observable in order to approximate its length and in order to prevent the crack from reaching a critical length and undergoing catastrophic failure. This required a surface finish smoother and more polished than a normal rolled plate finish. One of the 6- × 1-in surfaces and the two adjacent side surfaces of each bar were ground, in most cases with 4000-grit silicon carbide paper. The grinding was done on a Buehler Ecomet 4 variable speed grinder/polisher. To prevent edge cracks from forming, the edges required an ~0.1-in edge break from 4000-grit silicon carbide paper to reduce the stress concentration effects of the sharp edge. Manually polishing an item the size of these bars is no small matter. A refined technique was needed to keep the bars flat and parallel while providing the surface finish required over the large area. Even with this surface finish, several bars initiated cracks at an edge before generation occurred at an induced flaw in the center of the 6- × 1-in surface.

4.2 Crack Initiation and Extension

All fatigue testing was done on an Instron 1332 servo hydraulic testing machine with an 8500 plus controller. An MTS three-point and four-point bend fixture, in combination with rollers sized in accordance with the loading required, was used for all cyclic fatigue. The four-point bend fixture was used for all crack initiation and extension. The three-point bending fixture was used during the extension of the cracks after the bars were painted. A small scratch from a razor blade was placed in the center of each bar prior to cyclic fatigue (because of the hardness of steel and titanium, a diamond-tipped indenter was required for those specimens). This scratch created a local defect which acted as a stress concentration site, increasing the likelihood that initiation would take place in the center of the bar. The loop-shaping parameters for the closed-loop servohydraulic monitoring were adjusted to provide optimum cycling conditions. Using the four-point bending calculation equation and the four-point critical stress intensity equation, the loads required to initiate and extend a crack were calculated for each of the test materials.

Four-Point Bending Calculation:

$$\sigma = \frac{(3PL)}{(4bd^2)},\tag{1}$$

where

P = load,

L = outer span,

b = width,

p =thickness, and

 $\sigma = \text{stress}.$

Four-Point Critical Stress Intensity Equation:

$$\frac{\frac{3}{2}P(S_1 - S_2)}{BW^{\frac{3}{2}}} x \left(\frac{ax\pi}{W}\right)^{\frac{1}{2}} x f(a/W), \tag{2}$$

where

S = span,

a = crack length,

W = specimen thickness, and

$$f(a/W) = \frac{3(a/W)^{1/2} \left[1.99 - (a/W)(1 - a/W)x(2.15 - 3.93 a/W + 2.7 a^2/W^2) \right]}{2(1 + 2 a/W)(1 - a/W)^{3/2}}.$$
 (3)

Tables 1–4 present the polishing, crack initiation, and crack extension data for the four materials. During crack initiation, the scratch was observed with a flashlight until a visible crack was evident. Visible dye penetrant was utilized on the scratches of some specimens to assist in the detection of crack initiation and progression. The specimen was then removed from the machine, and the crack was measured via optical microscopy. Once the crack length was determined, it was further cyclically loaded with adjusted loading parameters that favored high cycle fatigue. The crack was once again observed with a flashlight until it had extended to a length of ~0.25 in. At this point, the crack was considered acceptable for preparation of its final length.

The crack depths were then estimated using an eddy current crack detection unit. By using the crack depth and length, accurate "thumbnail" models of the crack cross sections could be drawn. This helped estimate how much material to remove during the next step in order to reduce the length of the cracks to the desired amount.

4.3 Creation of Fatigue Cracks

Although the test matrix calls for only six fatigue-cracked specimens of each material, generating cracks of a known size on the open face plane (not an edge or a corner) of a material is considerably tedious and involves a multitude of specimens for destructive evaluation. Some

Table 1. Polishing, crack initiation, and crack extension data for aluminum bars.

Bar No.	Polish Before Cycling (SiC grit)	R Value	Cycling Load (lb)	(±) (lb)	Cycles	Result
1	1000	0.28	3575	2000	2000	No crack
		0.28	3575	2000	000	No crack
		0.28	3575	2000	10,000	Cracked, but also has edge crack
2	1000	0.28	3575	2000	10,000	No crack
		0.28	3575	2000	10,000	Cracked, but also has edge crack
		0.33	2000	1000	10,000	Extended to ~0.34 in
3	1000	0.28	3575	2000	14,000	Catastrophic fracture
4	1000	0.28	3575	2000	13,000	Catastrophic fracture
5	4000	0.41	3575	1500	13,000	Cracked ~0.2 in
		0.25	1000	600	50,000	Extended to ~0.26 in
6	4000	0.41	3575	1500	13,000	Cracked ~0.25 in
		0.25	1000	600	32,000	Extended to ~0.275 in
7	4000	0.41	3575	1500	5000	No crack
		0.41	3575	1500	6400	Cracked ~0.3 in
		0.2	1500	1000	7000	Extended to ~0.4 in
8	4000	0.41	3575	1500	16,500	Cracked ~0.21 in
		0.25	1250	750	10,000	Extended to ~0.275 in (curved)
9	4000	0.48	3575	1250	10,000	No crack
		0.41	3575	1500	10,000	No crack
		0.28	3575	2000	5000	Cracked ~0.25 in
		0.25	1000	600	40,000	Extended to ~0.325 in
10	4000	0.41	3575	1500	10,000	No crack
		0.41	3575	1500	5000	Cracked ~0.2 in
		0.25	1000	600	40,000	Extended to ~0.275 in

Note: Indicates that the bar was later used for FPI measurements.

cracks must be opened destructively to insure that the cyclic loading utilized is generating a uniform, semicircular, thumbnail surface crack. All the materials were bare during crack initiation and extension and pretreated before painting. The generation of the cracks involves many steps: initiating a precrack in the correct location, growing that precrack to a size larger than that which is desired, and grinding and polishing the specimen faces until the cracks are the correct sizes. Issues arise when attempting to achieve a specific crack length. In the case of this test matrix, three sizes were selected: 0.2, 0.1, and 0.025 in. In each case, a specific step-by-step procedure was followed. Grinding removed material from the cracked surface of the test specimens. All of the grinding was performed on a Mark surface grinder. The grinding data is presented in tables 5–8. The specimens were then hand-polished to remove the smeared material from the grinding step (the removal is never uniform; it is a function of grinding parameters and the number of specimens being ground). The polishing was performed on a Buehler Ecomet 4

Table 2. Polishing, crack initiation, and crack extension data for magnesium bars.

Bar No.	Polish Before Cycling (grit)	R Value	Cycling Load (lb)	(±) (lb)	Cycles	Result
1	4000	0.1	687.5	562.5	20,000	No crack
-	1000	0.1	750	625	10,000	No crack
		0.11	875	700	7500	Cracked 0.225 in
		0.14	400	300	20,000	Extended to 0.25 in
2	4000	0.11	875	700	10,000	Cracked 0.14 in
		0.14	400	300	150,000	Extended to 0.275 in
3	4000	0.11	875	700	10,000	Cracked 0.12 in
		0.14	400	300	90,000	
			550	450	15,000	Extended to 0.25 in
4	4000	0.11	875	700	10,000	Cracked 0.18 in
		0.14	400	300	70,000	Extended to 0.22 in
5	4000	0.11	875	700	10,000	Cracked 0.185 in
		0.14	400	300	80,000	Extended to 0.255 in
6	4000	0.11	875	700	10,000	Cracked 0.15 in
		0.14	400	300	75,000	
		0.1	550	450	10,000	Extended to 0.26 in
7	4000	0.1	825	675	20,000	Cracked 0.09 in
8	4000	0.1	825	675	33,000	Cracked 0.09 in

Note: Indicates that the bar was later used for FPI measurements.

Table 3. Polishing, crack initiation, and crack extension data for titanium bars.

Bar No.	Polish Before Cycling	R Value	Cycling Load	(±)	Cycles	Result
	(grit)		(lb)	(lb)	_	
1	1200	0.1	6600	5400	4000	Broke at 4000
2	1200	0.1	5500	4500	10,000	No crack
		0.1	5500	4500	4000	No crack
		0.1	5500	4500	5000	Broke at edge crack
3	1200	0.1	5500	4500	7500	Cracked 0.23 in
4	1200	0.1	5500	4500	10,000	No crack
		0.1	5500	4500	6700	Cracked 0.17 in
		0.1	3000	2500	20,000	No extension
		0.1	4000	3250	2500	Cracked 0.28 in
5	1200	0.1	5500	4500	10,000	No crack
		0.1	5500	4500	4872	Three edge cracks observed,
						small crack in the groove
6	1200	0.1	5500	4500	10,000	No crack
		0.1	5500	4500	1200	Cracked 0.295 in
7	1200	0.1	5500	4500	8300	Cracked 0.25 in
8	1200	0.1	5500	4500	13,500	Cracked 0.28 in
9	1200	0.1	5500	4500	10,000	Cracked 0.28 in

Note: Indicates that the bar was later used for FPI measurements.

Table 4. Polishing, crack initiation, and crack extension data for steel bars.

Bar No.	Polish Before Cycling	R Value	Cycling Load	(±)	Cycles	Result
	(grit)		(lb)	(lb)		
1	4000	0.1	6600	5400	7000	Short crack ~0.11 in
		0.45	6600	2500	8000	Extended to 0.25 in
2	4000	0.1	6600	5400	11,000	Cracked 0.18 in
		0.45	6600	2500	5500	Extended to 0.275 in
3	4000	0.1	6600	5400	7500	Short crack
		0.45	6600	2500	7000	Extended to 0.25 in
4	4000	0.1	6600	5400	10,000	Short crack
		0.32	6600	3400	3600	Extended to 0.225 in
5	4000	0.1	6600	5400	8000	Cracked 0.18 in
		0.45	6600	2500	5500	Extended to 0.25 in
6	4000	0.1	6600	5400	5600	Short crack, barely noticeable
		0.45	6600	2500	12,000	Extended to 0.225 in

Note: Indicates that the bar was later used for MPI measurements.

with silicon carbide paper. Then, the specimens were examined with optical microscopy and scanning electron microscopy in conjunction with FPI to determine the actual crack length. This procedure was repeated incrementally until all the specimens had the correct crack lengths. In all, six specimens of each material were precracked, with two specimens for each crack length. Testing the lower limit of detectability of FPI and MPI (0.025 in) proved extremely difficult. Quite often, the 0.025-in cracks were polished away in an attempt to reduce the size of a longer crack. The removal of even minute amounts of material at the crack front of a thumbnail crack has a considerable impact on crack length. The final stage in specimen fabrication proved to be even more disconcerting. It is important that the specimens do not have a polished smooth surface. Instead, they should have a surface consistent with the components they represent, i.e., typical aviation parts. Therefore, the final step was to provide the specimens with a typical 125 root-mean-square surface finish. This surface finish was applied with a Buehler belt grinder with 225-grit paper. The application of this surface finish removes a great deal of material and must be accounted for before finalizing the crack size. If it isn't, the smallest cracks are completely removed during this process. Once the cracks had the correct lengths, nondestructive inspection (NDI) was performed on the bars, and fluorescent light measurements were taken to get baseline values. FPI was performed on the aluminum, magnesium, and titanium, and MPI was performed on the steel. Subsequent to the baseline measurement, all bars except the titanium were pretreated with their respective coatings. Schematics of the incremental grinding and polishing for each of the specimens can be found in the appendix. The schematics in the appendix represent only the crack plane and are a enlargement of the cross section of the component (figure 2).

Table 5. Aluminum grinding data.

Bar No.	Machine Removed	0.01	0.05	0.05	0.011	0.012	0.01	0.015	0.008	0.006	0.005	0.003	Final Crack Length After Surface Finish Was Applied (in)
5	Crack length	1	0.202	1	1	ı	ı	1	1	1	1	1	0.218
9	Crack length		1	0.153	1	0.172	0.157	1	1	1	0.12	1	0.037
7	Crack length			0.29	0.278	0.275	0.257	0.175 0.127		0.098	1		0.098
8	Crack length		1	0.196	0.195	0.157	0.15	1	1	1	0.115	0.102	0.098
6	Crack length		1	0.247	0.237	0.224	0.171	1	0.092	1	1	1	0.047
10	Crack length	1	1	0.203	-	_	1	-		1	-	1	0.225

Table 6. Magnesium grinding data.

Bar No.	Machine Removed	0.015	0.015	0.015 0.015 0.005	900'0	Final Crack Length After Surface Finish Was Applied
						(in)
1	Crack length 0.182 0.165 0.15	0.182	0.165	0.15	0.1	0.10
2	Crack length	1	0.199	-		0.199
3	Crack length	-	0.202			0.202
9	Crack length 0.198 0.1	0.198	0.1	-		0.100
7	Crack length	1	1	-		0.025
8	Crack length	-				0.025

Table 7. Titanium grinding data.

Bar No.	Machine Removed	0.015	0.015	0.005	0.01	0.007	0.01	0.015	0.03	0.03	0.04	0.03	0.01	0.01	0.02	0.01	0.007	Final Crack Length After Surface Finish Was Applied
																		(in)
3	Actual	1			0.0105 0.0035	0.0035	0.005	0.007	0.007 0.0115 0.012		0.0155	-						0.200
	removed		_															
	Thickness		0.468	0.468	0.4575 0.454	0.454	0.449	0.442	0.4305 0.4185	0.4185	0.403							
	Crack length	0.222	0.217	0.245	0.23	0.245	0.24	0.24	0.23	0.225	0.2			-				
4	Actual	1	-	0.0025	0.004	0.0045	900.0	0.004	0.0135	0.0125	0.016	0.015	0.005	1	0.013	0.0055	0.0055	0.028
	removed		_															
	Thickness		0.465	0.465 0.4625 0.4585 0.454	0.4585	0.454	0.448	0.444	0.444 0.4305 0.418	0.418	0.402	0.387	0.382		0.369	0.3635	0.358	
	Crack length	0.27	0.245	0.3	0.27	0.265	0.26	0.265	0.265	0.24	0.225	0.21	0.202	1	0.15	0.13	0.098	
9	Actual			0.007	0.007 0.0045 0.004	0.004	0.005	0.005	0.0135 0.0115	0.0115	0.016	0.0155	0.0065		0.012	0.0055	0.0055	0.102
	Removed		_															
	Thickness	0.4695		0.4625 0.458	0.458	0.454	0.449	0.444	0.4305 0.419	0.419	0.403	0.3875	0.381		0.369	0.3635	0.358	
	Crack length	0.275	1	0.268	0.25	0.265	0.265	0.265	0.255	0.245	0.25	0.21	0.197	1	0.15	0.14	0.11	
7	Actual	1		0.0005	0.004	0.0035	0.0055	0.0055 0.0125		0.012	0.017	1	I		0.016	0.0235	1	0.030
	removed		_															
	Thickness		0.4625	0.4625 0.462	0.458 0.4545	0.4545	0.449	0.4435 0.431		0.419	0.402				0.386	0.3625		
	Crack length	0.25	0.23	0.237	0.235	0.265	0.26	0.245	0.24	0.238	0.195	_		-	0.19	0.09		
8	Actual	1		0.003	0.005	0.004	0.005	900.0	0.011	0.0135	0.016	0.014	0.0055		0.013	0.0055		0.102
	removed		_															
	Thickness		0.465	0.462	0.457	0.453	0.448	0.442	0.431	0.4175	0.4015	0.3875	0.382		0.369	0.3635		
	Crack length	0.245	0.265	0.26	0.245	0.265	0.26	0.26	0.265	0.26	0.235	0.215	0.196		0.15	0.102		
6	Actual	1	-	0.001	0.004	0.0045	0.005	900.0	0.0125	0.011	0.0185	0.014	0.0055		I		I	0.202
	removed		_															
	Thickness		0.4635	0.4635 0.4625 0.4585 0.454	0.4585	0.454	0.449	0.443	0.4305 0.4195		0.401	0.387	0.3815					
	Crack length	0.25	0.219	0.262	0.235	0.29	0.285	0.272	0.27	0.285	0.26	0.24	0.215	0.202			1	

Table 8. Steel grinding data.

Bar No.	Machine Removed	0.1	0.2	0.025	0.02	0.03	0.02	0.02	0.005	Final Crack Length After Surface Finish Was Applied (in)
1	Actual removed	0.0137	0.0128	0.0195	_	0.3534	0.0134		_	0.025
	Thickness	0.4148	0.402	0.3825	_	0.3534	0.34	_	_	_
	Crack length	0.25	0.215	0.2		0.13	0.025	_	_	_
2	Actual removed	0.0129	0.0139	0.0192	0.0133	0.0183	0.0099	0.011	0.003	0.100
	Thickness	0.4141	0.4002	0.381	0.3677	0.3494	0.3395	0.3285	0.3255	_
	Crack length	0.3	0.27	0.25	0.225	0.19	0.15	0.12	0.1	_
3	Actual removed	0.0131	0.0144	0.0205	0.003	0.0218	0.0196	_		0.030
	Thickness	0.4139	0.3995	0.379	0.376	0.3542	0.3346	_	_	_
	Crack length	0.25	0.25	0.225	0.195	0.155	0.03	_	_	_
4	Actual removed	0.0137	0.0153	0.0207		0.0243	_	_	_	0.090
	Thickness	0.4133	0.398	0.3773	—	0.353	—	_	—	_
	Crack length	0.25	0.215	0.19		0.09	—	_	_	_
5	Actual removed	0.0145	0.0169	0.0211				_		0.185
	Thickness	0.413	0.3961	0.375	—	—	—	_	—	_
	Crack length	0.25	0.215	0.195		—		_	—	_
6	Actual removed	0.0144	0.0177	_	_	_	_	_	_	0.185
	Thickness	0.4131	0.3954	_	—	—	—	—	—	_
	Crack length	0.225	0.2	_	_	_	_	_	_	_




Figure 2. Schematic of the cross section of a typical fatigue-cracked test specimen depicting the incremental removal of material from the top surface and its corresponding effect on cracklength reduction.

4.4 Light Optical Photometer

A certified inspector typically interprets indications. Since there can be considerable variation in interpretation of an indication from inspector to inspector, a light photometer was employed to detect the brightness of the indications and to measure any effect of the paint. This makes the FPI results considerably more quantitative than qualitative. There still exists some qualitative interpretation, however, as the photometer can not easily distinguish an intense, sharp, clear indication from a more intense but less sharp indication, typically referred to as "fuzzy." Indications are fuzzy when excess penetrant bleeds out from a crack. This occurs for several reasons, which include residues left behind in and around the crack, cleaner left behind from inadequate rinsing (or long evaporation times for solvent use), and water left behind from rinsing and inadequate drying. The equipment utilized for this program was the Photo Research, Model UBD, PR-1500 Spectra Spotmeter, Photomultiplier-Tube Optical Photometer. The data was acquired in foot-lamberts (FL), equivalent to 0.3183 candles/ft². Satisfactory results are obtained from readings with a large difference between the background fluorescence value and the indication fluorescence value, coupled with sharp distinct crack indications. Background values will vary slightly based upon available background light (if it is not completely eliminated).

5. Materials Pretreatment

The Ti-6-4 specimens were painted bare, but the other three materials had pretreatments applied as on typical aviation components manufactured from these materials. The steel specimens were cadmium coated IAW-SAE-AMS-QQ-P-416, Type II, Class II. The magnesium specimens were coated with Tagnite 8200 coating at a thickness of 0.32 mil. The aluminum specimens were anodized IAW MIL-A-8625. Following their respective pretreatment, the specimens underwent NDI to record baseline measurements for the crack sizes utilized.

6. FPI/MPI and Light Measurements

The penetrant materials included Sherwin water-washable HM-607 (sensitivity level 3) penetrant and Zyglow ZP-4B developer. The MPI was performed in a full wave direct current wet bath booth using 14A Magnaflux particulate with a particle concentration of 0.35 in a standard centerfuge. The flux density was set to 58–60 G. The light intensity for the inspection was set at 1400 candle-W² at 18 in. Post inspection processing involved degaussing and a solvent wash. FPI was performed in accordance with ASTM-E-1417 (7) and MPI in accordance with ASTM-E-1444 (8).

Brightness measurements were taken with a PR-1500 Spectra* spotmeter optical photometer. The measurement of light intensity has units of FL. For consistency in the light measurements (the photometer is very sensitive), the unit was calibrated before each use. With the blacklight placed next to the photometer, the center of the blacklight beam was focused on the platform. Using a Spectroline† hand held digital radiometer, the light beam was adjusted until the radiometer gave a reading of $10,500~\mu\text{W/cm}^2~(\pm500)$ with the spotmeter focused on the radiometer panel. The bars were placed on the platform one at a time, and the lens was focused on the crack. The spot was placed on one of the crack ends, and the reading was recorded. The spot was then placed on an area adjacent to the crack end, and a background measurement was taken. After all the measurements were taken the cracks were digitally recorded.

Once the FPI had been performed, the bars were cleaned to prevent the penetrant from drying in the crack. It is very difficult to remove dried penetrant from a crack. An ARL standard cleaning procedure was followed. First, the bars (Al, Mg, Ti) were placed in sonic tank with an NSK (Nakanishi, Inc.) cleaner (a blend of dentured alcohol and methylene chloride) for 5 min. Then they were placed in a drying oven for 5 min. Next, they were taken out of the oven and placed in another sonic tank filled with dimethyl formamide for 5 min. Then, they were rinsed with warm tap water and put back in the oven to dry. Finally, they were placed in a sonic tank filled with acetone for at least 1 hr. This very thorough procedure was not always necessary and was altered when conditions warranted. As stated previously, the steel bars were cleaned in a solvent wash after MPI.

7. Painting

The bars were painted to a dry film thickness of 1–1.5 mil with an epoxy primer (MIL-P-23377). New CARC was then applied to a dry film thickness of 2–2.5 mil for the topcoat (MIL-C-64159). After the paint was applied, the bars were air dried for 1 week and baked at 150 °F for 1 week. Once the coating system had been applied, FPI/MPI was performed on the bars, and brightness measurements of the cracks were taken.

8. Crack Extension After Painting

One bar of each crack length for each material was extended. The same set up as when the cracks were originally extended was used, except a three-point bend fixture was used instead of a

^{*}PR-1500 Spectra is a registered trademark of Photo Research, Inc.

[†]Spectroline is a registered trademark of Spectronics Corporation.

four-point bend fixture. Three-point bending calculations were tabulated for the bars showing the estimated required loads to extend each crack 0.5 in. After the extension, the cracks were inspected via FPI, and light measurements with the spotmeter were recorded. It is important to note that extending cracks with paint on them is much more difficult than extending bare bars. The paint masked the crack's true length and made it difficult to see the crack during the extension process. The painted-bar crack extension data can be observed in table 9.

9. Plastic Media Blasting

The aluminum, titanium, and magnesium bars were plastic media blasted (PMB) with Type V acrylic (thermal) plastic media IAW MIL-P-85891 (9). The original test matrix blasts the primer first and blasts the substrate after FPI. Even after attempting PMB on numerous actual aviation components and adjusting parameters such as air pressure, angle, and distance, blasting to the primer on the specimens could not be accomplished. The plastic media either removed nothing, or it removed the top coat and primer at the same time, which doesn't allow for the separation of the two coating layers. The bonding between the primer and the topcoat proved to be much stronger than that of the actual components. Consequently, only one FPI iteration could be performed on the bars, and no differentiation could be made between the top coat and primer.

The various types of plastic media utilized in PMB must be discussed. PMB facilities typically use a single type of plastic media, which they use for all of their PMB work. Most U.S. Department of Defense facilities use either Type II or Type V media. Type V media is not as hard as Type II media and is gentler on substrates. Type V media is more commonly used on aircraft. In some cases, Type II might be hard enough to deform the surface of a soft metal and smear material over a crack. Type II is recommended for steel-only surfaces.

ARL has evaluated PMB prior to FPI cleaning. The study ARL performed involved Type II media, which demonstrated good performance for harder metals. For this project, Type V (softer and gentler than Type II) was used. It was found that Type V can be detrimental to FPI and can mask the presence of cracks, especially in softer materials. When striking a surface, the softer plastic is able to deform and wedge itself into the crack. This effectively masks the crack and blocks any penetrant from getting in. The cracks in the aluminum and magnesium samples could easily be seen under the microscope and, in some cases, even without the aid of magnification; however, no indications were revealed during FPI. Titanium is much harder than aluminum and magnesium and so PMB did not appear to affect the titanium as much as the other samples. The titanium crack is also much narrower than the other two metals, which makes it more difficult for the plastic media particles to wedge into the crack. PMB also didn't seem to affect the smaller cracks as much as the larger ones—even the 0.025-in cracks of the aluminum and magnesium showed indications during FPI after PMB. This could also be due to the crack width being larger at longer crack lengths.

Table 9. Data after paint crack extension.

	Length	Length	Cyling		Total	
Bar No., Length	Extension (in)	Extension (in)	Load (lb)	(‡)	Cycles	Notes
Al no. 10, 0.2	0.2		476	390	10,000	No crack
		0.26	476	390	17,201	Complete
Al no. 8, 0.1	0.1		432	350	10,000	No visible cracking of paint, placed marker dots to monitor growth
			432	350	50,000	No visible cracking
			432	350	145,103	No crack observed with FPI or microscopic inspection
			486	398	180,000	Changed to 10% reduction, crack can be seen, est. at 0.1 in, marked ends and
						attempt to extend
		0.15	486	398	205,002	Complete
Al no. 9, 0.025	0.03		429	351	40,000	No visible crack
		0.083	429	351	175,001	Complete
Ti no. 9, 0.2	0.2	0.275	2409	1971	686	Crack extended, complete
Ti no. 6, 0.1	0.1	0.15	1645	1346	3800	Crack extended and done, used parameters for bar no. 8
Ti no. 7, 0.025	0.025	0.3	1440	1178	14,414	Crack extended longer than 50 mil limit, done
Mg no. 3, 0.2	0.2	0.201	242	198	0009	Crack visible, no growth observed
	0.2	0.202	242	198	20,000	Crack visible, no growth observed
	0.2	0.25	242	198	59,998	Complete
Mg no. 6, 0.1	0.1	0.1	219	179	20,000	No visible crack
		0.125	219	179	49,995	Crack visible
		0.13	219	179	61,003	Crack visible
		0.15	219	179	75,002	Complete
Mg no. 7, 0.025	0.025		225	184	40,002	No visible crack
			225	184	100,001	Crack visible, needs more extension
		0.052	225	184	115,001	Complete
St no. 6, 0.2	0.185	0.25	2413	1947	3063	Complete
St no. 2, 0.1	0.1	0.145	1655	1354	7064	Complete
St no. 3, 0.025	0.03		1358	11111	21,349	No visible crack
		0.075	1358	11111	50,501	Complete

Notes: All lengths after crack extension were estimated using a stereo microscope. Loop shaping parameters: Prop = -0.449. Int = 3.09. Deriv = 0.947.

Both the extended and unextended bars were stripped with PMB. On the bars with crack extensions, some extension of the cracks could be observed through the paint during and after the extension process. However, when the paint was stripped off via PMB, the cracks were not detectable by FPI. This indicated that the PMB was directly responsible for the decline in performance.

10. Chemical Removal of Paint

After PMB, the bars were placed in Brulin Industrial Safety Strip 5896B hot tank paint stripper and allowed to soak for ~24 hr. They were then removed and cleaned with solvent so FPI could be performed to see if there was any change. As indicated in the previous section, the plastic media was getting wedged into the magnesium and aluminum cracks, and the FPI was yielding affected indications. After soaking in paint stripper for 24 hr, there still were no visible indications. This demonstrated that the material within the crack, the Type V plastic media, was not dissolved or displaced by the stripper. To refresh the indications, the cracks needed to be mechanically opened. This involved placing the specimens back on the mechanical test stand and loading them to a deflection of about 1/8 in. After doing this, all bars again revealed indications of the cracks during subsequent FPI. When loading, the bars were first placed with the crack face in compression and then turned over with the crack face placed in tension. This needed to be completed on the extended as well as the unextended samples.

11. Results

11.1 Aluminum

The brightness measurements for aluminum can be found in table 10. The greatest intensity measurements came from the initial bare baseline condition. This condition also generally yielded the highest difference between the crack intensity and the background intensity. Figure 3 shows an optical photograph of bare aluminum crack no. 7. This is typical of the cracks formed in the aluminum material used for this study. The typical results for the FPI indications in the baseline condition are visually represented in figure 4. Figure 5 depicts the typical location of the spotmeter in relation to the cracks. After the bars were anodized, the intensities and the difference between the crack and background intensities were reduced. Figure 6 shows specimen no. 7 with typical visual FPI results after anodizing. No brightness measurements were taken after the coating system had been applied to the bars because no indications could be observed. Figure 7 shows specimen no. 7 with typical FPI visual results. No crack can be observed and

Table 10. Aluminum spotmeter readings.

Specimen	Spotmeter Indication		Spotmeter Background			er	After Pretreatment			After Painting	After Painting	
Identification	Measurement		Measurement	Difference	e Pretreatment	tment	Background	Difference		Measurement	Background	Difference
Al no. 6 – 0.025	1.68×10^{1}	101	1.92×10^{-1}	16.608	1.50×10^{0}	× 100	4.59×10^{-1}	1.041	Not v	Not visible	Not visible	1
Al no. $7 - 0.1$	10.30×10^{1}	10^{1}	$1.54\times10^{\text{-1}}$	102.85	6.70×10^{0}	: 100	6.57×10^{-1}	6.043	Not v	Not visible	Not visible	
Al no. $5 - 0.2$	3.64×10^{1}	101	1.32×10^{-1}	36.268	6.05×10^{1}	; 10 ¹	2.55×10^{-1}	60.245	Not v	Not visible	Not visible	
Al no. 9 – 0.025	1.29×10^{1}	101	$1.27\times10^{\text{-1}}$	12.773	3.96×10^{0}	: 100	6.95×10^{-1}	3.265	1			
Al no. 8 – 0.1	4.79×10^{1}	101	1.23×10^{-1}	49.577	3.52×10^{0}	; 10°	6.12×10^{-1}	2.908			1	
Al no. 10 – 0.2	11.42×10	10^{1}	$1.93\times10^{\text{-1}}$	114.01	2.98×10^{1}	: 101	6.33×10^{-1}	29.167	1		1	
					After Paint	Paint	After Paint		After Me	After Mechanical	After Mechanical	
Specimen Identification	After Plastic Media Blast Measurement		After Plastic Media Blast Background	a Difference		per	Stripper Background	Difference	-		Flexing Background	Difference
Al no. 6 – 0.025	Not visible	ble	Not visible		Not visible	sible	Not visible		2.34	2.34×10^{1}	2.22×10^{1}	1.2
Al no. 7 – 0.1	Not visible	ble	Not visible		Not visible	sible	Not visible		2.82	2.82×10^{1}	1.20×10^{1}	16.2
Al no. 5 – 0.2	Not visible	ble	Not visible		Not visible	sible	Not visible		10.48	10.48×10^{1}	1.15×10^{1}	93.3
Al no. 9 – 0.025			1				1	1			1	
Al no. 8 – 0.1											-	
Al no. $10 - 0.2$			1	1			1	1	-		I	
							•					
				ě				After		After Extension	7	u
		After Crack		Arter Extension	Arter Extension		Extension and Mechanical	Extension and Mechanical		and Chemical Stripper	al and Chemical Stripper	
Specimen Identification	After Crack Extension	Extension Background		PMB Difference Measurement	PMB Background	Difference	Flexing Measurement	Flexing Background	Difference	Processing Measurement	<u> </u>	Difference
Al no. 6 – 0.025	1			1		1	1		1	1		
Al no. $7 - 0.1$												
Al no. 5 – 0.2	-						1	-		1	1	
Al no. 9 – 0.025	2.54×10^{1}	1.49×10^1	10.5	Not visible	Not visible		14.83×10^0	0.43×10^{0}	14.4	18.56×10^{0}	2.28×10^{0}	16.28
Al no. 8 – 0.1	1.53×10^{1}	0.77×10^{1}	7.6	Not visible	Not visible		15.7×10^{0}	0.25×10^{0}	15.45	22.32×10^{0}	2.66×10^{0}	19.66
Al no. $10 - 0.2$	2.13×10^{1}	1.87×10^{1}	2.6	Not visible	Not visible		8.89×10^{0}	0.28×10^{0}	8.61	14.90×10^{1}	3.00×10^{1}	119
Notes: All measurements were obtained with FPI	ents were obtained	4 with FPI	ì	Ì		Ì	ì				Ì	

Notes: All measurements were obtained with FPI. All measurements are in units of foot-lamberts.




Figure 3. Al bar no. 7 after initiation and extension (shows crack at its final length).




Figure 4. FPI of Al bar no. 7 after initiation and extension.




Figure 5. Al bar no. 7 illustrating the manner in which the brightness measurements were acquired. The top dot represents the area the spotmeter was focused for the background measurement, and the bottom dot represents the area from which the crack measurement was acquired.




Figure 6. FPI of Al bar no. 7 crack after anodizing.




Figure 7. FPI of Al bar no. 7 crack after painting.

extreme background fluorescence from the paint absorbing the penetrant is evident. No brightness measurements were taken after PMB because zero indications were observed during FPI. The typical results are shown for specimen no. 7 (figure 8). Note how the crack has no visible infiltration of the penetrant. After the bar was processed in paint stripper and mechanically flexed, the crack was again apparent (figure 9). The brightness measurements taken for bars 8, 9, and 10 after chemical paint stripper processing were recorded after the cracks were flexed on the mechanical testing machine. Before they were flexed, no indications were visible. The resulting indications for cracks 8, 9, and 10 after this process can be observed in figure 10. Note again the extreme background fluorescence, resulting in low contrast between the background and the indications.

11.2 Titanium

Figure 11 presents an SEM micrograph of a typical bare titanium crack after initial extension. The corresponding brightness measurements for titanium can be found in table 11. The initial baseline measurements yielded the highest values of any category, and the difference between the crack intensity and the background intensity for this group yielded the highest contrast. The typical resultant FPI is visual depicted in figure 12. Figure 13 shows the typical areas where the light measurements were recorded. No indications were observed after the paint was applied, so no readings were recorded. Figure 14 presents the typical visual FPI results after paint was applied. The brightness measurements taken after the painted bars were extended were much




Figure 8. FPI of Al bar no. 7 after PMB. The crack can be observed visually, but no indication can be observed.




Figure 9. FPI of Al bar no. 7 performed after the bar had been processed in paint stripper and after the bar had been mechanically flexed.




Figure 10. FPI of Al bar nos. 8, 9, and 10—the bars with cracks extended ~0.050 in after painting—performed after the bars had been painted and the cracks mechanically flexed.




Figure 11. Titanium bar no. 6—0.1-in crack after initial crack extension.

Table 11. Titanium spotmeter readings.

3.30 × 10 ¹ 1.25 × 10 ¹ 52.875 Not visible Not measured	Specimen	Initial Crack Measurement	Initial Crack Background Measurement	Difference	After Painting Measurement	After Painting Background	Difference	After Plastic Media Measurement	After Plastic Media Background	Difference
1.57 × 10 ⁻¹ 69.243 Not visible Not measured 1.06 × 10 ⁻¹ 61.85 1.66 × 10 ⁻¹ 101.434 1.68 × 10 ⁻¹ 73.652 1.48 × 10 ⁻¹ 73.652 1.48 × 10 ⁻¹ 73.652 1.48 × 10 ⁻¹ 73.652 1.50 × 10 ⁻¹ 0.03 × 10 ⁻⁰ 0.03 × 10 ⁻⁰ 1.89 2.46 × 10 ⁻¹ 0.09 × 10 ⁻⁰ 60.01 1.89 2.46 × 10 ⁻¹ 0.03 × 10 ⁻⁰ 24.57 1.89 2.46 × 10 ⁻¹ 0.03 × 10 ⁻⁰ 0.05 × 10 ⁻¹ 1.89 2.46 × 10 ⁻¹ 0.03 × 10 ⁻¹ 0.05 × 10 ⁻¹ 1.89 2.46 × 10 ⁻¹ 0.03 × 10 ⁻¹ 0.05 × 10 ⁻¹ 1.89 2.46 × 10 ⁻¹ 0.03 × 10 ⁻¹ 0.05 × 10 ⁻¹ 1.80 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 1.80 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 1.80 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 1.80 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 1.80 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 1.80 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 1.80 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 1.80 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 1.80 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 1.80 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 1.80 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 1.80 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 1.80 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 0.05 × 10 ⁻¹ 1.80 0.05 × 10 ⁻¹ 0.		3.30×10^{1}	1.25×10^{-1}	32.875	Not visible	Not measured	-	Not visible	Not measured	
1.06 × 10 ⁻¹ 76.694 Not visible Not measured 1.50 × 10 ⁻¹ 61.85 1.66 × 10 ⁻¹ 101.434 1.48 × 10 ⁻¹ 73.652 1.48 × 10 ⁻¹ 73.653 1.48 × 10 ⁻¹ 73.653 1.48 × 10 ⁻¹ 70.05 × 10 ⁻¹ 70.05 × 10 ⁻¹ 1.48 × 10 ⁻¹ 70.05 × 10 ⁻¹ 70.05 × 10 ⁻¹ 1.48 × 10 ⁻¹ 70.05 × 10 ⁻¹ 70.05 × 10 ⁻¹ 1.50 × 10 ⁻¹ 70.05 × 10 ⁻¹ 70.05 × 10 ⁻¹ 70.05 × 10 ⁻¹ 1.50 × 10 ⁻¹ 70.05 × 10		6.94×10^{1}	1.57×10^{-1}	69.243	Not visible	Not measured		2.10×10^{0}	0.7×10^{-1}	2.03
1.50 × 10 ⁻¹ 61.85 1.66 × 10 ⁻¹ 101.434 1.48 × 10 ⁻¹ 73.652 1.48 × 10 ⁻¹ 73.652 1.48 × 10 ⁻¹ 73.652 Processing Background Difference Measurement Background Difference Not measured 1.36 × 10 ⁻¹ 0.027 × 10 ⁰ 60.01 0.07 × 10 ⁰ 0.39 6.01 × 10 ⁻¹ 0.09 × 10 ⁰ 60.01 0.06 × 10 ⁰ 1.89 2.46 × 10 ⁻¹ 0.03 × 10 ⁰ 24.57 After Extension PMB and PMB, and PMB ackground Mechanical Flexing Mech		7.68×10^{1}	1.06×10^{-1}	76.694	Not visible	Not measured	1	8.45×10^{0}	0.6×10^{-1}	8.38
1.66 × 10 ⁻¹ 101.434 1.48 × 10 ⁻¹ 73.652 1.48 × 10 ⁻¹ 73.652 1.48 × 10 ⁻¹ 73.652 Processing Background Difference Measurement Background Difference Not measured 1.36 × 10 ¹ 0.09 × 10 ⁰ 60.01 0.05 × 10 ⁰ 0.39 6.01 × 10 ¹ 0.09 × 10 ⁰ 60.01 0.06 × 10 ⁰ 1.89 2.46 × 10 ¹ 0.09 × 10 ⁰ 60.01 After Extension PMB, and PMB, and PMB and PMB and PMB and PMB and PMB and PMB and Mechanical Flexing M		6.20×10^{1}	$1.50\times10^{\text{-1}}$	61.85			1		1	1
1.48 × 10 ⁻¹		10.16×10^{1}	1.66×10^{-1}	101.434	-	1	1	1	1	1
After Paint Stripper		7.38×10^{1}	1.48×10^{-1}	73.652			1	1	1	1
Mechanical Flexing										
Processing Mechanical Flexing Mechanical Flexing Mechanical Flexing Mechanical Flexing Mechanical Flexing Difference Not measured — 1.36 × 10¹ 0.027 × 10⁰ 13.573 0.07 × 10⁰ 0.39 6.01 × 10¹ 0.09 × 10⁰ 60.01 0.06 × 10⁰ 1.89 2.46 × 10¹ 0.03 × 10⁰ 24.57 — — — — — — — — — — — — — — — PMB After Extension, PMB, and PMB, a		After Paint Stripper	After Paint Stripper		After	After		After	After Crack	
Not measured		Processing Measurement	Processing Background	Difference	Mechanical Flexing Measurement	Mechanical Flexing Background	Difference	Crack Extension	Extension Background	Difference
0.07 × 10° 0.39 6.01 × 10¹ 0.09 × 10° 60.01 0.06 × 10° 1.89 2.46 × 10¹ 0.03 × 10° 24.57		Not visible	Not measured		1.36×10^{1}	0.27×10^{-0}	13.573	1	1	1
0.06 × 10° 1.89 2.46 × 10¹ 0.03 × 10° 24.57		0.46×10^0	0.07×10^{0}	0.39	6.01×10^{1}	0.09×10^{0}	60.01	1	1	1
After Extension		1.95×10^{0}	0.06×10^{0}	1.89	2.46×10^{1}	0.03×10^{0}	24.57	1	Ι	1
After Extension			I	1				11.44×10^{0}	2.29×10^{0}	9.15
After Extension			-	1	-		1	8.79×10^{0}	2.62×10^{0}	6.17
After Extension								15.47×10^{0}	3.05×10^{0}	12.42
After Extension										
Marian					After Extension,	After Extension,		After Extension,	After Extension,	
Background Difference Measurement Background Difference — — — — — — — — — — — — — — — Not measured — — — — Not measured — 6.26 × 10° 0.70 × 10° 6.49 Not measured — 2.26 × 10° 0.83 × 10° 2.177		After Extension PMB	After Extension PMB		PMB, and Mechanical Flexing	PMB, and Mechanical Flexing		PMB, Flexing, and Chem Stripper	PMB, Flexing, and Chem Stripper	
		Measurement	Background	Difference	Measurement	Background	Difference	Measurement	Background	Difference
Not measured		1	Ι	1	-		_	-	_	1
Not measured							I		1	1
Not measured — 6.56×10^{0} 0.70×10^{-1} 6.49 Not measured — 2.26×10^{0} 0.83×10^{-1} 2.177			_		-		-	_	_	I
Not measured — 2.26 × 10° 0.83 × 10° 2.177		Very faint	Not measured	1	6.56×10^{0}	0.70×10^{-1}	6.49	8.48×10^{0}	$0.09 imes 10^0$	8.39
Not managed 2 00 0 101 0 00 0 101 20 22		Not visible	Not measured	-	2.26×10^{0}	0.83×10^{-1}	2.177	9.89×10^{0}	0.04×10^{0}	9.85
100 measured — 2.00 × 10 0.00 × 10 20.72		Very faint	Not measured		2.08×10^{1}	0.80×10^{-1}	20.72	26.31×10^{0}	0.06×10^{0}	26.25

Notes: All measurements were obtained with FPI. All measurements are in units of foot-lamberts.




Figure 12. FPI of titanium bar no. 6—0.1-in crack after initial crack extension.




Figure 13. FPI of titanium bar no. 6 showing areas where brightness measurements were taken. The top spot is the brightness of the crack, and the bottom spot (below the crack) is where the background reading was taken.




Figure 14. FPI of titanium bar no. 6 after painting.

dimmer than the initial measurements. The difference between the crack measurement and the background measurement was also greatly reduced. During FPI, only faint indications could be visually observed (figure 15). Titanium was the only material out of the three that demonstrated visible indications after PMB. Figure 16 shows an optical micrograph depicting the crack in titanium bar no. 6 after PMB. The indications were faint compared to the baseline measurements, and in some cases, portions of the crack length were masked completely. Ultimately, the titanium bar cracks required mechanical flexing on the mechanical test frame (like the aluminum and magnesium). Figure 17 shows the resultant visual FPI of titanium bar no. 6 after PMB and mechanical flexing. After chemical-stripper processing, the results were similar to those after the crack extension of ~0.05 in. These results are depicted in figure 18.

11.3 Magnesium

The magnesium bar brightness measurements can be found in table 12. An optical micrograph of the bare magnesium crack no. 2 is shown in figure 19. This is typical of the cracks in the magnesium material utilized is this work. The typical results for the FPI indications in the baseline condition are shown in figure 20. Figure 21 depicts the typical location of the spotmeter in relation to the cracks. The Tagnite pretreatment process tended to increase dramatically the brightness of the indications. Figure 22 presents the visual FPI results on bar no. 2 after Tagnite pretreatment. This pretreatment also absorbed a considerable amount of penetrant, which resulted in high background brightness values. This could be due to the characteristics of the Tagnite in the vicinity of a crack. The pretreatment was visibly nonuniform in this area, which




Figure 15. FPI of titanium bar no. 6 after the painted bar had been extended by 0.5 in.




Figure 16. Optical micrograph of titanium bar no. 6 showing the extended crack after PMB.




Figure 17. FPI micrograph of titanium bar no. 6 after PMB and mechanical flexing. Initial FPI produced no visible indication after PMB.




Figure 18. FPI micrograph of titanium bar no. 6 after PMB and chemical-stripper processing. The results are similar to those after painting and crack extension.

Table 12. Magnesium spotmeter measurement.

Notes: All measurements were obtained with FPI. All measurements are in units of foot-lamberts.




Figure 19. Magnesium bar no. 2 with a 0.2-in crack length.




Figure 20. FPI micrograph of cracked Mg bar no. 2 after the crack was initiated and extended to the desired length.




Figure 21. FPI micrograph of cracked Mg bar no. 2 depicting the typical locations of the light measurements. The top spot is the brightness of the crack, and the bottom spot (below the crack) is where the background reading was taken.




Figure 22. FPI micrograph of cracked Mg bar no. 2 after the Tagnite coating.

would certainly affect the capillary action of the penetrant. The increase in the overall signal from the indications far outweighed the increased background signal, and the result was clear, bright indication of the cracks. No brightness values were recorded after the coating system had been applied to the bars, since no indications could be visually observed. The typical FPI visual results after coating are shown in figure 23. No crack can be observed, and extreme background fluorescence from the paint absorbing penetrant is evident. After extension of the cracks under the coating system, FPI revealed that the cracks became visible. These indications were not nearly as bright as the baseline values, and the background was much higher due to the absorption of the penetrant by the coating system. Figure 24 depicts the typical visual FPI micrographs after crack extension under the coating system. No brightness measurements were recorded after PMB because zero indications were observed during FPI. Paint-stripper processing did not alleviate this condition and the cracks had to be mechanically flexed to dislodge the plastic media from the cracks. Figure 25 represents the typical FPI results after the crack was mechanically flexed to dislodge the plastic media. The brightest measurements were generally yielded from the extended bars after the paint was chemically stripped. However, these bars were flexed, and it is difficult to reliably assess the effect that mechanical flexing had on the characteristics of the crack that yielded the initial brightness, regardless of the fact that the crack length wasn't changed during flexing. Figure 26 depicts the visual FPI results after mechanical flexing of this group.




Figure 23. FPI micrograph of cracked Mg bar no. 2 after the application of the coating system. No crack can be observed, and the absorption of the penetrant by the coating is evident.




Figure 24. FPI micrograph of cracked Mg bar nos. 3, 6, and 7 after crack extension under the coating system. Cracks can be observed; however, the absorption of the penetrant by the coating is still evident.




Figure 25. Typical FPI results after PMB, chemical processing, and mechanical flexing to remove the plastic media from within the cracks. Results shown for Mg bar no. 2 after soaking in paint stripper ~24 hr.




Figure 26. Typical FPI results after crack extension under the coating, PMB, mechanical flexing, and chemical-stripper processing. Results shown for Mg bar nos. 3, 6, and 7 after soaking in paint stripper ~24 hr.

11.4 Steel

MPI was the NDI method evaluated for crack detection in steel. Since a crack does not have to be open to the surface to be detected with MPI, the coating on the steel bars did not undergo PMB or chemical stripping like the other bars. Multiple layers of paint were applied, and MPI was performed after each layer until no cracks could be observed using the standard MPI parameters. The MPI results for steel can be observed in table 13. A typical fatigue crack generated in steel is depicted in figure 27. Initially, FPI was performed to compare the steel with the rest of the materials. The typical visual FPI results on the steel bars can be observed in figure 28. Figure 29 depicts the areas where the light measurements and the background measurements were recorded. Baseline light measurements were recorded during MPI processing. Figure 30 depicts the typical visual results of the baseline group. After cadmiumplating pretreatment, the MPI-generated light measurements were only slightly less than the initial baseline values. After the first application of the coating system, only half of the cracks could be observed. A 0.2-in crack (the longest crack length) and a 0.1-in crack were two of the observable indications. All three of the measured indications were just barely visible to the eye and could not be photographically recorded. The 0.025-in specimens were immeasurable. Figure 31 presents the typical visual results after the cracks were extended 0.05 in. The results showed that the indications were extremely dim and barely detectable. However, the indications were greater than before the cracks were extended. After the second layer of paint, no indications were observable on any bar (figure 32). To investigate if the specimens would show indications with a higher magnetic field, the flux density was increased to 90 G and then gradually increased to 130 G. No indications were observable even at this extreme flux density.

Table 13. Steel spotmeter measurements.

								Т								
	Difference		0.42	0.41		1	0.768	6	Steel Bar Paint	mickiless 10tal (mil)	9.6	7.8	8.4	8.2	9.1	8.2
After Painting	Background	Not measured	4.3×10^{-1}	4.4×10^{-1}	Not meas.	Not measured	6.2×10^{-1}		Steel Bar Paint	mickness 1st Coat (mil)	3.9	3	3.4	3.1	3.8	3
After Painting	Measurement	Not visible	$8.5\times10^{\text{-1}}$	8.5×10^{-1}	Not visible	Not visible	8.3×10^{-1}	į	Steel							
	Difference Me	4.247 N	4.415	3.969	4.85 N	3.772 N	3.32			Difference	_	-	Ι	_	1	_
	Diff	4.	4.	3.	4	3.	3		gu							
After Pretreatment	Background	4.33×10^{-1}	2.55×10^{-1}	4.81×10^{-1}	7.80×10^{-1}	3.08×10^{-1}	1.80×10^{-1}	3	After 2nd Coating	Applied Background	Not measured	Not measured	Not measured	Not measured	Not measured	Not measured
After Pretreatment	Measurement	4.68×10^{0}	4.67×10^{0}	4.45×10^{0}	5.63×10^{0}	4.08×10^{0}	3.50×10^{0}		After 2nd Coating	Applied Measurement	Not visible	Not visible	Not visible	Not visible	Not visible	Not visible
	Difference	4.488	5.765	7.331	4.949	6.042	7.052			Difference				0.88	69.0	1.61
Initial Crack Background	Measurement	1.42×10^{-1}	$1.25\times10^{\text{-1}}$	1.49×10^{-1}	1.71×10^{-1}	1.38×10^{-1}	1.48×10^{-1}	ē.	After Crack	Extension Background		1	I	0.55×10^{0}	0.98×10^{0}	0.69×10^{0}
Initial Crack	Measurement	4.63×10^{0}	5.89×10^{0}	7.48×10^{0}	5.12×10^{0}	6.18×10^{0}	7.20×10^{0}		After Crack	Extension Measurement			1	1.43×10^{0}	$1.67 imes 10^{0}$	2.30×10^{0}
Specimen Identification	Crack Length	ST no. 1 – 0.025	ST no. 4 – 0.090	ST no. 5 – 0.185	ST no. 3 – 0.030	ST no. 2 – 0.100	ST no. 6 – 0.185		Specimen	Crack Length	ST no. 1 – 0.025	ST no. 4 – 0.090	ST no. 5 – 0.185	ST no. $3 - 0.030$	ST no. 2 – 0.100	ST no. 6 – 0.185

Notes: All measurements were obtained with MPI. All measurements are in units of foot-lamberts.



Figure 27. Bar no. 3 after initiation and crack extension—typical fatigue crack generated in steel.




Figure 28. Steel bar no. 6 after initial crack extension—0.2 in crack. Typical FPI visual results on steel fatigue cracks.




Figure 29. Typical FPI micrograph of steel showing the areas where brightness measurements were taken on this bar. The top dot (on the crack) is the crack brightness measurement location. The bottom dot (below the crack) is the background measurement location.




Figure 30. Bar no. 6 after the initiation and crack extension. Typical baseline visual MPI micrograph on steel.




Figure 31. Bar no. 6 after the 0.050-in crack extension. Typical visual MPI micrograph after crack extension.



Figure 32. Typical visual MPI micrograph after the application of the second layer of paint. All traces of the crack indication are gone.

12. Discussion

12.1 Scope

It was evident within the results that this study was overly aggressive in scope. The creation and use of the same set of specimens to evaluate the effect of NDI performed over paint while subsequently using these same specimens for the evaluation of PMB and chemical paint stripping produced coupled effects. The effect of one process on the value of the light measurement could not be completely separated from the effects of the subsequent processes. For instance, it was assumed that Type V PMB would be sensitive enough to remove just the topcoat and leave the primer unaffected. The cured paint conditions proved this assumption incorrect. It was also assumed that this PMB process would effectively remove the paint system and leave an adequately cleaned crack for FPI. The soft Type V PMB penetrated, wedged, and masked the cleaned cracks, especially those which were longer and wider. The subsequent chemical-stripping-process evaluation was affected by this lodged Type V plastic media. It was thought beforehand that any residual effect of the paint on the measured light value would be mostly removed by the PMB and completely removed by the chemical-stripping process, yielding the initial brightness values (or at least a very close approximation of those values). The results demonstrated that performing FPI over the paint was impossible. Type V media removed the paint but became lodged in the cracks. Even in subsequent chemical stripping, it could not bring back the cracks to their initial condition. The Type V media proved resistant to the chemical stripper. The dislodging of the plastic media from the cracks could only be accomplished by mechanical flexing of the crack. It was also not completely known whether this process was 100% effective. There might exist some residual plastic media within the cracks.

12.2 Effect of Performing FPI Over Paint

Performing FPI of cracks which were painted over proved futile. There existed no path for the penetrant to infiltrate and collect within the cracks, and the paint absorbed a great deal of penetrant, which led to high background fluorescence. FPI performed over paint when the cracks were extended proved only slightly more rational. Although fractures within the coating system resulting from extension of the cracks under the paint could be observed under microscopic examination, sound FPI of these cracks proved impossible. The paint absorbed the penetrant, which resulted in extreme background fluorescence of the entire area. This eliminated any contrast between the crack and the background. This contrast is solely responsible for drawing one's attention and leads to the observation of an indication. Additionally, the paint proved far too flexible to allow substantial amounts of the penetrant to collect within the crack. Essentially, the paint is flexible, and it closes on itself after removal of the stresses that extend or open a crack and fracture the paint. So even though fractures within the paint can be observed under microscopic examination, there exists very little opening for penetrant to flow into the

permanently deformed crack suggesting it is still open under the paint after removal of the stress). A stiffer, less compliant coating system may allow penetrant to collect within a crack; however, the coating system must also not absorb penetrant because that would still have a detrimental effect on the results.

12.3 PMB

The Type V media penetrates and lodges within the cracks of the materials tested. The larger the crack width, the more media becomes lodged. This type of media should not be used prior to FPI, as the cracks are either completely obliterated or greatly reduced in brightness.

12.4 Chemical Removal

This method should have effectively removed the residual paint from the PMB process. Since it was performed after the PMB process, the results were commingled. The stripper could not remove the plastic media, so the cracks were still masked. There is nothing to suggest that the chemical stripper itself causes a detrimental effect on the FPI process. However, since the chemical stripping was not done immediately after the FPI over the paint, it is not known whether chemical stripping could be an effective means of removing paint from cracks like those that were missed during a routine inspection and subsequently painted over.

13. Conclusions

13.1 FPI


- The process performed over paint is not conducive to revealing sharp, bright indications on materials and crack sizes used within this study. The paint system completely obliterated the indications and absorbed the fluorescent penetrant, which eliminated any contrast between the crack and the background fluorescence.
- The Type V media, although effective at removing the paint system in this study, is soft enough that it lodges within the cracks and significantly reduces the measured brightness of the indications.
- Chemical paint stripping is unable to remove the lodged plastic media from within the cracks.


13.2 MPI


• One layer of the coating system in this study greatly reduced the effectiveness of the inspection technique. Two layers of the coating system completely masked the crack even when MPI was performed with magnetic fields up to 130 G.


14. References


- 1. ADS-61-PRF. *Aeroautical Design Standard 61*. U.S. Army Aviation and Missile Command: Huntsville, AL, 2001.
- 2. MIL-A-8625. Anodic Coatings for Aluminum and Aluminum Alloys 1993.
- 3. SAE-AMS-QQ-P-416. Plating, Cadmium (Electrodeposited) 2002.
- 4. MIL-P-23377. Primer Coatings: Epoxy, High Solids 1994.
- 5. MIL-C-64159. Coating, Water Dispersible Aliphatic Polyurethane, Chemical Agent Resistant 2002.
- 6. ASTM-E-1444. Standard Practice for Magnetic Particle Testing Standard Practice for Magnetic Particle Testing. *Annu. Book ASTM Stand.* **2005.**
- 7. ASTM-E-1417. Standard Practice for Liquid Penetrant Examination. *Annu. Book ASTM Stand.* **2005**.
- 8. ASTM-E-1444. Standard Practice for Magnetic Particle Testing. *Annu. Book ASTM Stand.* **2005**.
- 9. MIL-P-85891. Plastic Media, for Removal of Organic Coatings 1998.





















































NO. OF

COPIES ORGANIZATION

1 DEFENSE TECHNICAL
(PDF INFORMATION CTR
ONLY) DTIC OCA
8725 JOHN J KINGMAN RD
STE 0944
FORT BELVOIR VA 22060-6218

- 1 US ARMY RSRCH DEV &
 ENGRG CMD
 SYSTEMS OF SYSTEMS
 INTEGRATION
 AMSRD SS T
 6000 6TH ST STE 100
 FORT BELVOIR VA 22060-5608
- 1 DIRECTOR
 US ARMY RESEARCH LAB
 IMNE ALC IMS
 2800 POWDER MILL RD
 ADELPHI MD 20783-1197
- 3 DIRECTOR
 US ARMY RESEARCH LAB
 AMSRD ARL CI OK TL
 2800 POWDER MILL RD
 ADELPHI MD 20783-1197

ABERDEEN PROVING GROUND

1 DIR USARL AMSRD ARL CI OK TP (BLDG 4600)

NO. OF COPIES ORGANIZATION

ABERDEEN PROVING GROUND

- 2 DIRECTOR USAATC AMSRD ARL WM MC B HARDISKY
- 4 DIRECTOR
 USARDECOM
 AMSRD AMR AE F M
 K BHANSALI (2 CPS)
 M KANE (2 CPS)
- 2 DIR USARL AMSRD ARL WM MC S GRENDAHL

INTENTIONALLY LEFT BLANK.